Operating Instructions



All Purpose Canopy

Assembly Requirement:

Minimum of two people and a sledgehammer.

- 1. Once your location is designated, take the tent out of the bag and lay it out completely flat with the valence of the tent facing down. You must make sure that the area is free of electrical wires, pipes, and any obstacles that might be underground.
- 2. The sides of the tent will have one hole, rope, and stake. Each corner should have one hole, two ropes, and two stakes Hammer in a stake about 6 feet away from each hole in the canopy.
- 3. Connect one long pole and one short pole and layout next to each stake. The center pole(s) will be two long poles and one short pole. There is one center pole in a 20x20, two in a 20x30, and three in a 20x40.
- 4. Start in opposite corners. Insert side poles into pole holes in the canopy and raise them so that the bottom of the poles slants toward the center of the canopy. (Approx. 45 degrees)
- 5. Tighten the guy rope on the stake and continue with the corners and sides.
- 6. Raise the three-piece center pole(s) and insert it into the center pole hole. Raise to the upright position and tie the jump rope to a pole.
- 7. Tighten guy ropes and then set side poles to the upright position. Adjust pole positions and guy rope tension to stretch out the canopy properly. Protective covers are recommended for all stakes.

Dismantling:

- Loosen all guy ropes.
- 2. Spread out a drop cloth if needed.
- 3. Disassemble all side poles and put them in the bag according to size. Repeat this step for the center pole(s).
- 4. Roll the canopy up and put it back into the bag.

For any questions or concerns, be sure to contact us immediately. Thank you for your business!

1155 Route 9 Wappingers Falls, NY (845) 298-0011



1 Precision Road Danbury, CT (203) 744-2295

20' X 20' APC STAKES – 12 LONG POLES – 10 SHORT POLES – 9

20' X 30' APC

STAKES – 14

LONG POLES – 14

SHORT POLES – 12

20' X 40' APC

STAKES – 16

LONG POLES – 18

SHORT POLES – 15